

High Performance Foams Division

171 West St. Charles Road Carol Stream, IL 60188-2081 Tel: 630.784.6200 / Fax: 630.784.6201 www.rogerscorporation.com

BISCO® Silicones

Product Availability

PRODUCT mm (inch)	2.5 (0.10)	5.0 (0.20)	0.25 (0.01)	0.51 (0.02)	0.7 (1/32)	1.59 (1/16)	2.38 (3/32)	3.18 (1/8)	4.76 (3/16)	6.35 (1/4)	9.52 (3/8)	12.7 (1/2)	15.9 (5/8)	19.0 (3/4)	25.4 (1)
BF-2000								•	•	•	•	•			
BF-1000							•	•		•	•	•		•	
HT-870						•	•	•		•	•	•			
HT-800					• not red	•	•	•		•	•	•			
HT-820					•	•	•	•	•	•					
HT-840						•	•	•	•	•					
RF-120	•	•						A	A	A	A	A	A	A	A
IF-200		•						A	A	A	A	A	A	A	A
FPC						•	•	•	A	•					
HT-1240				A	•	•	•	•	A	A					
HT-1250				•	•	•	•	•	A	A					
HT-1260				A	•	•	•	•	A	A					
HT-1270					•	•	•	•	A	A					
HT-1500					not w/	•		•							
HT-1510						•	A	A							
HT-6210			not w/	not w/	not w/	not w/	not w/	not w/							
HT-6220			not w/ adhesive	not w/ adhesive	not w/	not w/	not w/	not w/							
HT-6135			not w/adhesive	not w/adhesive	•	•	•	•							
HT-6240			not w/ adhesive	not w/	•	•	•	•							
HT-6360				not w/	•	•	•	•							
HT-200									listed ii r two si		page	6. Also	availa	able wi	th
LEGEND															
•		RD PROI													
A					Custom	ier Servic	ce Repre	sentativ	e for ord	ering de	tails.)				
	PRODUC	CT NOT A	AVAILABL	.E											

The information contained in this Availability Sheet is intended to assist you in designing with Rogers BISCO Silicones. It is not intended to and does not create any warranties, express or implied, including any warranty of merchantability or fitness for a particular purpose or that the results shown in this Availability Sheet will be achieved by a user for a particular purpose. The user should determine the suitability of Rogers BISCO Silicones for each application.